




CESR off (17May2005)




Flat cable disconnected on DSP side (17May2005)




flat cable disconnected on PMT side (24May2005)




flat cable connected, HV cable disconnected on PMT side (24May2005)



beam pipe window covered (0659)



beam pipe window covered, PMT pc board isolated (0742)



beam pipe window not covered, PMT pc board isolated (0758)

BSM23W

Train 1 bunches

Pedestal subtracted

PMT HV=off

t=840