



2nd Board Installed, Gain 6, Channel 0 183 Bunches 2.75k Turns




Note: Clock 79 Used, First Board Used, Second ADC Disabled For All Measurements

2nd Board Not Installed, Gain 6, Channel 0, 183 Bunches, 2.75k Turns




Bunches 27,60,115,169,171 2nd Installed, Gain 6, Ch. 0, 65.5k Turns


RMS Values Per Bunch (v2)




RMS Values Per Bunch (v2)



RMS Values Per Bunch (v2)




RMS Values Per Bunch (v2)




Bunches 27,60,115,169,171 2nd Not Installed, Gain 6, Ch. 0, 65.5k Turns


RMS Values Per Bunch (v2)



RMS Values Per Bunch (v2)



RMS Values Per Bunch (v2)



RMS Values Per Bunch (v2)

